


WD 11 Wiring Diagram

WD 11

Schematic



Connections

% Voltage	Primary Volts		Connect lines to	Inter-connect
105.0%	218	252	X1, X2, X3	1-2
100.0%	208	240	X1, X2, X3	2-3
95.0%	198	228	X1, X2, X3	3-4
Secondary Volts		Connect lines to		Inter-connect
480		H1, H2, H3		
277		H1, H0	H2, H0	H3, H0