


WD 16 Wiring Diagram

WD16

Schematic



Connections

% Voltage	Primary Volts	Connect lines to	Inter-connect
105.0%	504	H1, H2, H3	1-2
102.5%	492	H1, H2, H3	2-3
100.0%	480	H1, H2, H3	3-4
97.5%	468	H1, H2, H3	4-5
95.0%	456	H1, H2, H3	5-6
Secondary Volts		Connect lines to	Inter-connect
		X1, X2, X3	
		X1, X6 X3, X6	