


WD 6 Wiring Diagram

WD 6

Schematic



Connections

% Voltage		Primary Volts								Connect lines to	Inter-connect
105.0%	218	242	252	437	483	504	604	630		H1, H2, H3	1
100.0%	208	230	240	416	460	480	575	600		H1, H2, H3	2
95.0%	198	219	228	395	437	456	546	570		H1, H2, H3	3
		Secondary Volts								Connect lines to	Inter-connect
	208	230	240	380	416	460	480	600		X1, X2, X3	
	120	133	139	220	240	265	277	347	X1, X0	X2, X0	X3, X0